

Lancia Ypsilon - Vibrationer og støj | HELLA

Lancia Ypsilon (843) Alle modeller indtil VIN 3027759 Årgang: 2003 - 2011
Vibrationer og støj fra bagakslen Hvis ovennævnte fejl konstateres, kan det skyldes styrene til håndbremsekablerne. Vibrationerne eller støjen forekommer især på ujævn vej. Her kan de ske, at kablet har for stort spillerum i holderne og dermed kan klapre ved kraftige bevægelser i undervognen. I så fald skal kablet løsnes fra holderne, spillerummet skal udlignes med en filtstrimmel, og kablet sættes på plads igen. Desuden anbefales det at sikre holderne med en kabelbinder. Beskadigede dele skal udskiftes i samme forbindelse.

Ypsilon (843)

All models up to VIN 3027759

Model year: 2003 - 2011

Vibrations and noises on the rear axle

Whenever the above-mentioned problem is detected, its cause can often be found in connection with the cable control guides of the handbrake cable. These vibrations or noises mainly occur when driving takes place on uneven roads and surfaces.

It can happen that the cable has too much play within its supporting bracket and, consequently, it begins to rattle when there is increased suspension movement.

In such cases the cable is to be loosened from its mounting bracket, the excessive play corrected by means of a felt strip and then the cable once again secured in position.

It is also recommended to secure the supporting bracket with a cable tie.

Any damaged parts resulting from the problem are also to be replaced during such repair work.

