

# **Lexus IS F - Viskerne virker ikke | HELLA**

**Lexus IS F Årgang: 07/2007 - 07/2011 Viskerne virker ikke. Hvis der for ovennævnte modeller klages over, at viskerne ikke virker, kan det skyldes en fejl på viskerarmen. Et for lille tilspændingsmoment af viskerarmenes møtrikker kan være årsagen til, at viskerne ikke virker. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret. Værkstedet udskifter viskerarmenes møtrikker og spænder dem med det korrekte tilspændingsmoment.**

## **IS F**

**Model year: 07/2007 to 07/2011**

### **Failure of the windscreen wipers.**

If the windscreen wipers fail on the vehicle listed above, the cause may be a defect in the wiper arm.

In this case, insufficient torque in the wiper arm nuts is responsible for the failure of the windscreen wipers.

The vehicle manufacturer has already addressed the issue and notified owners of affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

The wiper arm nuts are replaced at specialist garages and attached with the correct torque.