

Mazda 3 - Viskerne virker ikke | HELLA

Mazda3 Årgang: 07.01.2008 - 31.03.2009 Viskerne virker ikke Hvis der for ovennævnte modeller klages over, at viskerne ikke virker, kan det skyldes en dårlig stelforbindelse til viskermotoren. Fejlen afhjælpes ved, at værkstedet monterer en ekstra stelledning til viskermotoren. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.

3

Model year: 07/01/2008-31/03/2009

Windscreen wiper fails

If a complaint is made about the windscreen wiper failing in the above vehicle, this may indicate an insufficient earth connection in the windscreen wiper motor.

In order to remedy this, an additional earth cable for the windscreen wiper motor is mounted in the specialist workshop.

The vehicle manufacturer has already addressed the issue and notified owners of affected models.

For various reasons, however, it must be assumed that not all vehicles have been checked or modified.