

Mazda 5 - Støj fra de midterste luftdyser | HELLA

Mazda Mazda 5 Årgang: 2010 til 2012 Støj fra de midterste luftdyser i instrumentpanelet I ovennævnte modeller kan der forekomme støj/vibrationer fra de midterste luftdyser i instrumentpanelet, når varme-/klimaanlægget er i funktion. Denne effekt forstærkes ved høj blæserhastighed. Årsagen er en konstruktionsbetinget funktionsfejl i de midterste luftdyser i instrumentpanelet. Bilfabrikanten har allerede taget sig af problemet og kan levere en ændret midterdyse til instrumentpanelet (se tabel). Reservedele Beskrivelse Res.nr. Antal Klimaanlæg/ varmesystem Midterdyse til instrumentpanelet, højre C513 64 930A1 Midterdyse til instrumentpanelet, venstre C514 64 930A1

Mazda 5

Model year: 2010 to 2012

Noise coming from the centre air nozzles in the dashboard area

With the above-mentioned vehicles, noises/vibrations can occur in the centre air nozzles in the dashboard area when the heating/air conditioning system is switched on. This effect is amplified at high speed.

This is caused by a construction-related malfunction in the dashboard centre air nozzle for the heating and air conditioning system.

The vehicle manufacturer has already recognised the problem and is offering a modified dashboard centre air nozzle (see table).

Spare parts (SP)