

Nissan Juke (F15) - Fejl i sædevarme | HELLA

NissanJuke (F15)Årgang: 2010Modeller med sædevarmeFejl i sædevarmeHvis der for ovennævnte modeller klages over fejl i sædevarmen, kan årsagen være et defekt eller fejlbehæftet ledningsbundt.Følgende modeller kan være berørt heraf:Produktionsperiode fra 16.08.2010 til 30.09.2010Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.I tilfælde af fejl kan bilfabrikanten levere en adapterledning.Adapterledning: Res.nr. 87019 1KL0A

Juke (F15)

Model year: 2010

Vehicles with seat heating

Malfunctioning of the seat heating.

If complaints are made about the functioning of the seat heating in the above-mentioned vehicles, a faulty or defective wiring harness should be considered as a potential cause of the trouble.

The following vehicles can be affected:

Production period from 16.08.2010 to 30.09.2010

[](#)The vehicle manufacturer has already taken up the problem and has notified the owners of the affected vehicles. Nevertheless, one may assume that for various reasons not all vehicles have been checked and repaired.

In the event of such malfunctioning, an adapter cable is available from the vehicle manufacturer.

Adapter cable: spare part (SP No.) 87019 1KL0A