

Opel Astra H - Klima­anl­ægget fungerer ikke | HELLA

Opel Astra H Årgang: 2004 - 2008 Mit klimaautomatik (ECC) Klima­anl­ægget fungerer ikke i automatisk funktion I ovenn­ævnte modeller kan det forekomme, at klima­anl­ægget kun fungerer i manuel funktion pga. en „softwarefejl“. I displayet vises så ofte en ukendt fejlmeddelelse (M1 - M5). Afhj­ælpning sker ved at foretage en software­opdatering. Fra bilfabrikantens side benyttes den ændrede software i biler fra følgende stel­nr.: W0L0AHL4882160266 - (fabrik Bochum) W0L0AHL0885117742 - (fabrik Antwerpen) W0L0AHL4888096223 - (fabrik Ellesmere Port)

Astra H

Model years: 2004 - 2008

With electronic climate control (ECC)

Air conditioning not working in automatic mode

In the above vehicles, "software failure" may be the cause that the air conditioning works only in manual mode. The display will then often show an incomprehensible error message (M1 - M5).

This can be remedied by a software update.

The vehicle manufacturer has already been using the modified software at the factory starting from the following VINs:

W0L0AHL4882160266 - (Bochum plant)

W0L0AHL0885117742 - (Antwerp plant)

W0L0AHL4888096223 - (Ellesmere Port plant)