

# Opel Astra H - Kølevæske i automatgearkassen | HELLA

**Opel Astra H Årgang: 2007 - 2008 Motor: 1,8i og 2,2i Med automatgear Kølevæske i automatgearkassen** En utæthed i motorens kølevæske køleren kan medføre, at der kommer kølevæske i automatgearkassens oliekredsløb. De autoriserede forhandlere kan på basis af kølerens produktionsdata kontrollere, om en given bil er berørt. Om nødvendigt udskiftes køleren som forebyggelse. Der skal tages hensyn til denne information ved servicering af ovennævnte modeller. Desuden skal det kontrolleres, om der allerede er kølevæske i automatgearkassens oliekredsløb.

## **Astra H**

**Model year: 2007 - 2008**

**Engine: 1.8 i and 2.2i**

**With automatic transmission**

## **Coolant in the automatic transmission**

Coolant can get into the oil circuit of the automatic transmission due to a leak in the coolant radiator.

Authorized dealers can use the production status of the radiator to check the extent to which a particular vehicle is affected. If necessary, the radiator will be replaced as a precaution.

This information should be taken into account when maintaining the vehicles mentioned above. Furthermore, the vehicle should be checked to see how much coolant is already in the oil circuit of the automatic transmission.