

Opel Astra H / Signum / Vectra C - Fejlkode: P0201 - P0204 | HELLA

Opel Astra H / Signum / Vectra C Årgang: 2004 - 2006 Motor: Z19DT / Z19DTH / Z19DTL / Z19DTJ Motoren går ujævnt, desuden kan motorkontrollampen lyse. Fejlkode: P0201 - P0204 Betydning: Indsprøjtningsdyse 1 – 4, funktionsfejl i kredsløb. Hvis ovennævnte problem forekommer i forbindelse med de lagrede fejlkoder, skal der først foretages en softwareopdatering af motorstyreenheden. Hvis det ikke medfører en forbedring, skal injektorernes stikforbindelser kontrolleres og om nødvendigt udskiftes med et forbedret stikledningsnet med et ledningstværsnit på 2,5 mm². Bilfabrikanten har allerede taget sig af problemet, fra motornummer: Z19DTH17000444 monteres der et forbedret ledningsnet i produktionen.

Astra H / Signum / Vectra C

Model year: 2004–2006

Engine: Z19DT / Z19DTH / Z19DTL / Z19DTJ

Engine jolts, the engine control lamp may illuminate

Error code: P0201–P0204

Indicative of:

Injection valve 1–4, malfunction in electric circuit.

If the issue listed above occurs in combination with the indicated error codes, an engine control unit software update should first be installed.

If this does not produce any improvement, the plug connectors should be checked and, as required, replaced by an improved connector cable set with a cable cross-section of 2.5 mm².

The vehicle manufacturer has already addressed the issue. A modified cable set is installed from engine identification number Z19DTH17000444.