

Opel Astra J - Afløb for kondensvand / Diverse elektriske fejl | HELLA

Opel Astra J Årgang: 2010 - 2012 Motor: Alle varianter Afløb for kondensvand / Diverse elektriske fejl Hvis der forekommer diverse elektriske fejl i ovennævnte modeller, kan det skyldes en defekt eller manglende afledning af kondensvand. Årsagen kan også være et luftfilterhus, der er beskadiget allerede i produktionen. Som følge af den mangelfulde afledning af kondensvand kan der trænge vand ind i BCM (Body Control Modul) og forårsage følgende fejl: Centrallåsen fungerer ikke Fejlfunktion for viskere Hornet lyder af sig selv Motoren kan ikke starte Fejlfunktion for karrosserisystemer Diverse fejlkoder Fejlen afhjælpes på følgende måde: Kontroller, om afløbet for kondensvand er i orden eller er klempt sammen Evt. monteres eller udskiftes afløbet for kondensvand Kontroller luftfilterhuset for skader/spor af vand, og udskift det om nødvendigt Kontroller BCM for vandindtrængen og korrosion, og udskift det i tilfælde af vandindtrængen Slet fejlhukommelsen Foretag en funktionstest

Astra J

Model year: 2010–2012

Engine: all variants

Condensation drain / various electrical faults

If there are any electrical faults in the above vehicles, these may be caused by a faulty or missing condensation drain.

Another cause may be an air distributor that was damaged during production.

A faulty drain may allow water to reach the BCM (Body Control Module), leading to the following faults:

- Central locking system does not work
- Wipers do not work
- Horn activates itself
- Engine will not start
- Body systems do not work

- Various fault codes

Proceed as follows to rectify the problem:

- Check that the condensation drain is present and whether it is broken
- If necessary, fit/replace the condensation drain
- Check the air distributor housing for damage/traces of water and replace if necessary
- Check the BCM for water ingress and corrosion and replace in the event of water ingress
- Clear the fault memory
- Carry out performance check