

Opel Astra J - Fejlkode P261A | HELLA

Opel Astra J Årgang: 2012 Motor: A17DTE / A17DTF Med elektrisk styret kølevæskepumpe Fejlkode P261A / Fejllampen for motorelektronik (SVS) lyser I ovennævnte modeller kan det forekomme, at fejllampen for motorelektronik lyser, og at fejlkoden P261A ligger i fejlhukommelsen. Fejlkoden gælder den elektrisk styrede kølevæskepumpe, der drives af motoren, og ikke den elektriske hjælpepumpe. Normalt er kølevæskepumpen i orden. Afhjælpning sker ved at foretage en opdatering af motorstyreenhedens software og udføre en visuel kontrol og en funktionstest.

Astra J

Model year: 2012

Engine: A17DTE / A17DTF

With electrically controlled coolant pump

Error code P261A /

Engine management system fault light (SVS) lights up

On the vehicles listed above, the fault light for the engine management system may light up and the the code P261A may be stored in error memory.

The error code refers to the electrically controlled coolant pump driven by the engine and not the electrical auxiliary pump.

The coolant pump is usually in working order.

To remedy the error, update the software for the engine control unit and carry out a visual inspection and function check.