

Opel Corsa C - Varmeapparat virker ikke | HELLA

Opel Corsa C Årgang: 2005 til 2006 Med klimaautomatik (ECC) og Triple Info Display (TID) Varmeapparat virker ikke ovennævnte modeller kan det ske, at varme-/klimaenlægget i nogle minutter efter start af motoren kun afgiver kold luft. Fejlen forekommer oftest, når udetemperaturen er lavere end 6 °C, og bilen tages i brug igen mindre end 2 timer efter, at den sidst har kørt. Årsagen kan være en „hardwarefejl“. Derved registrerer ECC en for høj udetemperatur og forsøger at køle i stedet for at varme. For at afhjælpe fejlen skal Triple Info Display udskiftes med en ændret version, og der skal indlæses en ny software. Biler efter stelnr. W0L0XCF0866074319 har allerede fra fabrikken en ændret hard- og software.

Corsa C

Model year: 2005 to 2006

With automatic air-conditioning (ECC) and Triple Info Display (TID)

Interior heating does not work

On the above mentioned vehicles it may occur that

the heating system/ air-conditioning system only produces cold air for a few minutes after starting the engine. The fault mostly occurs if the exterior temperature is below 6°C and the vehicle is started again within 2 hours (of parking it).

A "hardware bug" may be the cause.

As a result the ECC detects an excessively high exterior temperature and tries to cool instead of heat.

To rectify the problem the triple info display should be replaced with a modified variant and new software installed.

Vehicles from chassis no. W0L0XCF0866074319

already have modified hardware and software from the factory.