

# Opel Insignia - Fejlkode: C1221, C1222, C1223, C1224 | HELLA

**Opel Insignia Årgang: 2010 - 2011** Motorkontrollampen lyser **Fejlkode: C1221, C1222, C1223, C1224** **Betydning: Omdrejningssensorer, indgangssignal 0** Hvis fejlkoderne forekommer i forbindelse med ovennævnte problem, kan det tyde på en defekt styreenhedssoftware. Problemet kan ifølge bilfabrikanten løses ved at programmere motorstyreenheden med en ændret og forbedret software. Styreenhedens software kan kun opdateres af en autoriseret forhandler.

## Insignia

**Model year: 2010 - 2011**

**Engine warning light comes on**

**Error code: C1221, C1222, C1223, C1224**

These mean that the input signal of the speed sensors is 0.

If the error codes can be linked with the above-mentioned problem, this could point to faulty control unit software.

According to the vehicle manufacturer, the situation can be remedied by programming the engine control unit with revised and improved software.

Such updating of software is only to be carried out by an authorised dealer.