

Opel Meriva - B - En rude åbner af sig selv | HELLA

Opel Meriva B Årgang: fra 2010 En rude åbner af sig selv i ovennævnte modeller kan en rude åbne sig af sig selv, når en dør eller bagklappen åbnes. Det kan skyldes en fejl i softwaren i karrosseristyreneheden. Bilfabrikanten har allerede taget sig af problemet. Problemet kan ifølge bilfabrikanten løses ved at programmere karrosseristyreneheden med en ændret og forbedret software. Styreenhedens software kan kun opdateres af en autoriseret forhandler.

Meriva- B

Model year: from 2010 onwards

Window opens of its own accord

With the above-mentioned vehicle, it can happen that a window opens on its own when a door or when the hatchback is being opened.

This could be the result of faulty software in the body control unit.

The vehicle manufacturer has already addressed the issue. According to the manufacturer, reprogramming the body control unit with improved and modified software can remedy this problem.

Such updating of software is only to be carried out by an authorised dealer.