

Opel - Motorkontrollampen lyser | HELLA

Opel Alle modeller Alle modeller med dieselpartikelfilter Motorkontrollampen lyser Hvis den ovennævnte fejl påpeges af kunden, kan partikelfilteret være årsagen. Ikke mindst klages der over nedsat motoreffekt. Denne klage fremføres særligt for biler, der kører korte ture med mange koldstarter. Desuden kan der være lagret fejlkoden „P1901- Partikelfilter tryksensor”. Følg i så fald følgende fremgangsmåde:- For at udelukke andre fejlkilder skal alle relevante systemer og komponenter kontrolleres. Ved kontrollen skal man også være opmærksom på ledningerne og korrekt kontakt (korrosion i stikforbindelserne).- Hvis der ikke konstateres fejl her, skal der foretages en manuel regenerering af partikelfilteret. Bemærk! Følg bilfabrikantens anvisninger!- For at undgå følgeskader skal partikelfilteret være koldt.- Under regenereringen genereres der høje temperaturer i udstødningssystemet! Derfor må bilen ikke placeres på brændbart underlag. For at sikre en komplet reparation skal der også foretages en opdatering af softwaren. Derved forkortes intervallet for regenereringsprocessen betydeligt.

All models

All vehicles with diesel particulate filters

Illumination of the malfunction indicator lamp

If a customer complains about the above error, this could be caused by the diesel particulate filter. Not least of all, this problem would also cause a lack of power. This complaint has been observed even in vehicles that are used for short trips with many cold starts. The error code "P1901- Particulate Filter Pressure Sensor" could also be stored in memory. In this case, proceed as follows:

- To rule out other error sources, all relevant systems and components should be tested. During the testing, also pay attention to the wiring and check for problem-free contacts (corrosion in the plug connections).

- If no errors are discovered in these parts, the particulate filter should be regenerated by hand.

Caution! Follow the instructions of the vehicle manufacturer!

- To prevent subsequent damage, the particulate filter must be cold.
- The regeneration process produces high temperatures in the exhaust system! For this reason, do not park the vehicle on combustible surfaces.

To guarantee comprehensive repair, the software should also be updated. Therefore the interval for the regeneration process will be significantly shortened.