

Peugeot 307, 308, - Lygterne virker ikke | HELLA

Peugeot 307, 308, Expert Årgang: 11/2006 - 12/2008 Lygterne virker ikke. Selv om lyskontakten er tændt, kan det for ovennævnte modeller forekomme, at lygterne ikke lyser. Da styreenheden ikke registrerer, at kontakten er tændt, tændes lygterne ikke. På de autoriserede værksteder foretages der en software-opdatering af de berørte biler for at afhjælpe fejlen. Producenten er klar over problematikken og har allerede imødegået den med en tilbagekaldelsesaktion. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet udbedret.

307, 308, Expert

Model year: Nov. 2006 - Dec. 2008

Lighting failure

The vehicles mentioned above may experience a lighting failure despite the light being switched on.

The actuation of the switch by the control unit is not detected, so the lighting remains switched off.

This problem can be resolved by performing a software update at the authorized garage.

The vehicle manufacturer has already launched a recall campaign to deal with the problem. For various reasons, however, it must be assumed that not all vehicles have been modified.