

Peugeot 407 - Pollenfilter tilstoppet | HELLA

Peugeot 407 Årgang fra 2004 Højrestyrede modeller (RHD) Pollenfilter tilstoppet
Nedsat lufttilførsel til kabinen Hvis der i de ovennævnte modeller klages over nedsat funktion af blæsermotoren, og konstateres der desuden en nedsat luftstrøm til kabinen, kan årsagen være pollenfilteret. Selv om bilerne til dels kun har kørt mindre end 10.000 km siden seneste skift af pollenfilteret, kan pollenfilteret være tilstoppet. Problemet afhjælpes ved at montere et ændret pollenfilter. 1 stk. – pollenfilter: (reservedelsnummer) res.nr. 647904
Illustrationerne viser udførelsen for højrestyrede modeller i fodrummet i passagersiden.

407

Model year: from 2004

Right-hand drive (RHD)

Pollen filter clogged.

Reduced air flow into the interior of the vehicle.

If, on the above mentioned vehicles, there are complaints about a degradation in the function of the heater blower motor or air-conditioning blower motor and a reduced air flow is also apparent in the vehicle interior, the pollen filter is a possible cause of the problem.

Even though the vehicle may not have covered 10000 km since the last time the pollen filter was replaced, it still might be clogged again.

As a rectification measure fit the modified pollen filter.

One – pollen filter: (service part no.) ET no. 647904.

The figures show the “right-hand drive” design in the area of the passenger's footwell.

