

# Smart 451 - Kortslutning i kølevæskeafspærringsventilen | HELLA

**Smart451 (Pure+Passion) Årgang: 31.08.2010 - 02.06.2014 Kortslutning i kølevæskeafspærringsventilen**  
ovennævnte modeller kan der opstå kortslutning i kølevæskeafspærringsventilen til varmeapparatet som følge af slid. Ventilens funktion er at lukke for varmeapparatet, således, at den kolde motor hurtigere bliver varm, hvilket reducerer slitagen. Bilproducenten har konstateret problemet og tilbagekaldt bilerne til kontrol hhv. sætte ventilen ud af funktion. Det må antages, at flere årsager kan have medført, at ikke alle biler er kontrolleret hhv. repareret. Vær opmærksom på denne information, især ved klager over elektriske fejl.

**451 (Pure and Passion models)**

**Model year: 8/31/2010 - 6/2/2014**

## **Short circuit in coolant shutoff valve**

The above vehicles can experience a short circuit in the coolant shutoff valve of the heating system due to the effects of wear.

The job of the valve is to allow the cold engine to warm up faster by closing off the heating system in order to reduce mechanical wear and tear.

The vehicle manufacturer is already on top of the problem and has inspected the vehicles and deactivated the valves as part of a recall campaign.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

Please observe this bulletin, especially in conjunction with complaints received about electrical faults.