

Suzuki Alto - Kølevæsketermometret viser for lav værdi | HELLA

SuzukiAltoAlle modeller: 2002 til 2007Kølevæsketermometret viser for lav værdi.Hvis der i ovennævnte modeller vises ukorrekt kølevæsketemperatur, kan årsagen være en dårlig stelforbindelse via termostathusets holder.

Afhjælpning foretages ved at tilslutte stelkablet (se illustrationen) mellem termostathuset og termostathusets holder.-----

Desuden skal termostathuset kontrolleres for skader og om nødvendigt udskiftes.Reservedel: Res.nr.:1 stk.: Termostathus: 17690M79F20-----

Reservedele: Res.nr.:1 stk.: Stelkabel: 39313M820201 stk.: Bolt: 02142M05123

Alto

All models: 2002 to 2007

Value displayed on coolant temperature gauge is too low.

If these vehicles display an irregular coolant temperature value, the possibility of a bad ground connection to the thermostat housing bracket must be considered. To fix this problem, the ground cable (see figure) should be connected between the thermostat housing and the thermostat housing bracket.

Additionally, check the thermostat housing for damage and replace if necessary.

Spare part: (spare parts) - number:

1 unit: Thermostat housing: 17690M79F20

Spare parts: (spare parts) - number:

1 unit: Ground cable: 39313M82020

1 unit: Fastening bolt: 02142M05123

