

Suzuki Vitara - For høj kølevæsketemperatur | HELLA

Suzuki Vitara Alle modeller efter 07/96 Motorkode: H20A For høj kølevæsketemperatur, ujævn motorgang. I ovennævnte modeller kan en defekt hhv. trægt fungerede For høj kølevæsketemperatur medføre for høj kølevæsketemperatur hhv. dårlig motorgang. Hvis kølevæsketermostaten åbner trægt, vil cirkulation af kølevæsken blive nedsat, hvilket kan medføre ovennævnte symptom. For at afhjælpe fejlen skal ikke kun termostaten udskiftes med en ændret udførelse, men også termostathuset udskiftes med en ændret udførelse. Res.nr. 1 stk.: Res.nr.: 17670-77E10 termostat 1 stk.: Res.nr.: 17690-77E01 termostathus

Vitara

All models from 07/96

Engine code: H20A

A faulty or sluggishly operating coolant thermostat can result in an excessively high coolant temperature or a poorly running engine on the above mentioned vehicles.

If the coolant thermostat opens sluggishly, inadequate coolant circulation will affect the engine cooling system and can result in the above mentioned symptoms. To rectify the problem, it is necessary not only to fit the modified thermostat, but also to replace the thermostat housing with the modified thermostat housing.

Service part no (ET no.)

1 piece: ET no.: 17670-77E10 thermostat

1 piece: ET no.: 17690-77E01 thermostat housing