

Toyota Prius - Reduceret motoreffekt (nødprogram) | HELLA

ToyotaPrius +Årgang: 05/2010 – 11/2014Nedsat motoreffekt (nødprogram)For ovennævnte modeller klages der over, at advarselslamperne i instrumentgruppen tænder under kørslen, og at nødprogrammet aktiveres.Som følge af en softwarefejl kan hybridsystemet blive overhedet og slå fra under kørslen.Det medfører, at bilen skifter til nødprogrammet.Bilen kan kun køre med reduceret motoreffekt.Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet.Det må antages, at flere årsager kan have medført, at ikke alle biler er kontrolleret hhv. repareret.Mærkeværkstederne foretager en software-opdatering af de berørte biler.

Prius +

Year of manufacture: 05/2010 – 11/2014

Reduced drive power (emergency operation mode)

The complaint has been made that the warning lights in the instrument cluster light up and emergency operation mode is activated when the above vehicles are in motion.

Due to a software error, the hybrid system may overheat and switch off when the vehicle is in motion.

The vehicle then switches to emergency operation mode.

It is only possible to drive with reduced power.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The software for the relevant vehicles is to be updated at the specialist garage.