

Toyota Yaris / Verso S - Servostyringen fungerer ikke| HELLA

Toyota Yaris / Verso S Årgang Yaris: 11/2010 – 11/2011 Årgang Verso S: 08/2010 - 07/2011 Servostyringen fungerer ikke ovennævnte modeller kan servostyringen ophøre med at fungere. Årsagen kan være et defekt relæ i servostyringens styreenhed. I produktionen af styreenheden kan der evt. være kommet fugt i et relæ. Det kan medføre kortslutning, og dermed at servostyringen ikke fungerer. Styringen bliver tung, desuden informeres føreren om den manglende funktion med lys- og lydssignal (advarselsslampe og advarselstone). Selv om servovirkningen ikke fungerer, kan bilen stadig styres. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. På de autoriserede værksteder udskiftes det defekte relæ i de berørte biler. I Toyota-garantisystemet registreres reparationen under det pågældende stelnummer. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.

Yaris / Verso S

Yaris model year: 11/2010 to 11/2011

Verso S model year: 08/2010 to 07/2011

Failure of the power steering.

Failure of the power steering may occur in the vehicles listed above.

The cause may be a defective relay in the power steering control unit. During production of the control unit, it is possible that moisture entered a relay. This can lead to a short-circuit and thus cause the power steering to fail.

Steering is then heavy, and the failure is indicated to the driver by visual and acoustic means (warning light and beep). Despite the failure of the power steering assistance, the vehicle can still be steered.

The vehicle manufacturer has already addressed the issue and notified owners of affected models.

The defective relay in affected vehicles is replaced at specialist garages.

The repair is registered under the corresponding chassis number in the Toyota warranty system.

For various reasons, however, it must be assumed that not all vehicles have been checked or modified.