

# VW Golf 4 - Klimaanlæg virker ikke | HELLA

**VW Golf 4 Årgang: 1997 - 2005** Alle modeller med manuelt klimaanlæg Klimaanlægget virker ikke Hvis klimaanlægget hhv. kompressoren i ovennævnte modeller ikke virker, kan årsagen være en fejl/defekt ved udetempersensoren. Temperatursensoren sidder under torpedoaafdækningen i venstre side (i kørselsretningen) (fig. 1). Årsagen til fejlen kan være selve temperatursensoren eller ledningen (fig. 2), der kan være beskadiget af armen på viskermotoren. Sensoren kan testes for "plausibilitet" via måleværdiblokkene, dvs. at værdien fra sensoren kan sammenlignes med den faktiske omgivelsestemperatur ved hjælp af et diagnoseapparat. Fig. 1 Fig. 2

## Golf 4

**Model years: 1997 – 2005**

**All models with manual air-conditioning system**

### **Air-conditioning system not working**

Should the air-conditioning system and/or compressor not function properly in the above vehicles, a defect/fault in the area of the outside temperature sensor might be the cause.

The temperature sensor is situated to the left (in direction of travel) below the cowl screen (Fig. 1). The cause of the defect can either be the sensor itself or the connecting cable (Fig. 2), which has been damaged by the wiper motor linkage. The sensor can be checked for "plausibility" via the measured value blocks, i.e. it is possible to compare the sensor value with the actual value of the ambient temperature by using a diagnostics device.



Fig 1



Fig 2