

VW Sharan - ESP lamp lights up | HELLA

VW

Model year: until 2008

With electronic stability program (ESP)

ESP lamp lights up

If the ESP warning lamp lights up sporadically or permanently in the above vehicles, this may be caused by a faulty lateral acceleration sensor.



Figure 1

