

VW Touareg - Motorkontrollampen lyser | HELLA

VW Touareg 3,0i V6 (TDI) Model: (7L_) / (7P5) Årgang: 2010
Motorkontrollampen lyser
Motorkontrollampen i ovennævnte modeller lyser som følge af en defekt udstødnings-differenstryksensor. En defekt udstødnings-differenstryksensor mærkes ved f.eks. ujævn motorgang og/eller ved, at motorkontrollampen lyser. Hvis en defekt sensor ikke udskiftes, kan det medføre følgeskade (på f.eks. dieselpartikelfilter, motor etc.).
Reparationsvejledning: Udskift differenstryksensoren.
Udstødnings-differenstryksensor OE-nr. 059 906 051 A Hella nr. 6PP 009.409-031
Tilspændingsmoment (skruer) 3,5 Nm
Hvis sensoren allerede er udskiftet i forbindelse med en aktion fra fabrikanten, er det angivet med en mærkat i reservehjulsbaljen og dokumenteret i servicehæftet.

Touareg 3.0i V6 (TDI)

Model: (7L_)/(7P5)

Model year: 2010

Engine warning light illuminates

The engine warning light illuminates on the vehicles mentioned above due to a defective exhaust gas differential pressure sensor.

A defective exhaust gas differential pressure sensor may become apparent if the engine no longer runs smoothly and/or if the engine warning light illuminates, for example.

If a defective sensor is not replaced, this may lead to consequential damage (including on the DPF, engine, etc.).

Repair note:

Replace differential pressure sensor.

- Exhaust gas differential pressure sensor

OE no. 059 906 051 A