

Audi A3 - Heat output too low | HELLA

Audi

A3

Model years 1997 to 2003

All engines with cast-iron cylinder block

If a customer complains about the above error, this could be caused by contaminated engine coolant.

Spezialer für Kohlsysteme

cleaning agent for cooling towers

Nettoyant pour systèmes de refroidissement

Reiniger Water Systems

Limpador de sistemas de ar

Deliverables per system of work



Such contamination (rust, metal particles from the cast-iron block) blocks the small openings in the heat exchanger preventing flow.