

Audi Q5 - Noise from air-conditioning line

Audi

Q5

Model years: 2010 – 2016

Noise from air-conditioning line

The vehicles mentioned above may experience clattering noise coming from the engine compartment. If this happens, special attention should be paid to the lines of the air-conditioning system.

There is a possibility that the noise may be caused by insufficient clearance between the refrigerant line and coolant expansion tank.

This can be fixed by installing a modified refrigerant line and/or installing the line correctly.

