



Hyundai i20: noise from engine compartment

Data sheet

Manufacturer	Hyundai
Vehicle model	i20
Engine	All petrol engines
Model year	2009 - 2012
Symptoms	Mechanical noise from the engine compartment

Important safety note

Hyundai i20: engine noise or mechanical noise from the engine compartment

If you can hear mechanical noise from the engine compartment in above-mentioned vehicles, focus on the coolant pump in particular. A prematurely worn bearing may be causing the noise.

It is necessary to install a new coolant pump together with a modified belt pulley to resolve the situation and prevent further damage. We recommend you simultaneously replace the pump's drive belt.

Tip

We advise that you check the coolant pump for leaks as well as noise as part of general servicing and replace it if necessary.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.