

Lancia Ypsilon 843 - Malfunction "Third stop light" | HELLA

Lancia

Ypsilon 843

Model years: 2003 – 2011

Malfunction "Third stop light"

If the Lancia Ypsilon (Fig.1) is found to have a fault or partial failure (Fig.2) affecting the "third" stop light, the possible cause may be individual defective light sources.



Fig.1

Repair notes

We recommend the following procedure:

- Completely switch off the electrical system.
- Remove the faulty stop light. To do so, remove the covers (Fig.3) and unlock the clips (Fig.4).
- Then remove the light unit (Fig.5) and unplug the connector.



Fig.2





Fig.3



Fig.4



Fig.5

- Disconnect the bulb holder from the housing
- Remove the faulty bulbs and replace
- Re-assemble the third stop light in reverse order and install.

Then carry out a function test.

Spare parts required: 8GP 938 026-001 (W 2.3 W)

Note

To ensure a constant light pattern, we recommend replacing all bulbs in this situation.

Fig.6





Fig.8