



MCC Smart (451) - Replacing the cabin filter

Data sheet

Manufacturer	MCC
Vehicle model	Smart (451)
Engine	All models
Year of manufacture	2007 - 2015
Symptoms	Replacing the cabin filter

Important safety note

Changing the cabin/pollen filter

In the Smart 451, the cabin/pollen filter is changed from the driver's footwell.

To reach the cover of the evaporator/heater box, the hand must be moved behind the accelerator/brake pedal.

The cover can now be removed (unclipped) and the filter pulled out to the left.

Insert new filter (pay attention to installation position) and put cover back on/close cover.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only

for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.