

# **BMW Serie 5 (G30/G31) / Serie 7 (G11/G12) - La luz de freno se queda encendida | HELLA**

**BMW**


**Serie 5 (G30/G31) / Serie 7 (G11/G12)**

**Fecha fabricación: 05/2017**

**Con cambio automático**

**La luz de freno se queda encendida**

Si se detecta la problemática arriba mencionada, puede deberse a un defecto en la cabeza esférica del pedal de freno.



### **ⓘ Important safety notice**

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.