

Fiat Nuova Punto - Se enciende el testigo luminoso del ABS de manera esporádica | HELLA

Fiat

Nuova Punto

Código motor: 199 A3.000

Año de fabricación: 2005-2010

Se enciende el testigo luminoso del ABS de manera esporádica

En los vehículos arriba mencionados es posible que se encienda de manera esporádica el testigo luminoso del sistema antibloqueo. Al mismo tiempo ha quedado registrado el código de avería P0504 en la memoria de averías de la unidad de control del motor.

En algunos casos también puede encenderse el testigo luminoso del asistente de ayuda al arranque en pendiente.

Causa

Esta circunstancia puede deberse a una sujeción inadecuada de los contactos de clavija del enchufe situado en el interruptor del pedal del freno.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.