

OPEL Astra H - Pérdida de refrigerante | HELLA

OPEL

Astra H

Año de fabricación: 2002 - 2009

Pérdida de refrigerante

Fugas y daños en el condensador

Si se comprueba que los vehículos arriba mencionados pierden refrigerante, deberá prestarse especial atención al condensador.

Puede haberse producido cierta inestabilidad en la red del condensador provocada por la pérdida de algunas laminillas. Las vibraciones pueden producir contacto con otros componentes. Debido a ello se daña el condensador (imagen 1), perdiendo así su estanqueidad.

Además, es posible que el condensador se haya soltado de su soporte y que se apoye en el bastidor (imagen 2). Este hecho también podría provocar la falta de estanqueidad mencionada.






Figure 2

ⓘ Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.