

Peugeot Modelo: 307 - Se enciende el testigo luminoso del ABS | HELLA

Peugeot

Modelo: 307

Fecha de fabricación: a partir de 2006

Todos los modelos con ABS/ESP

Se enciende el testigo luminoso del ABS

Código de avería: 53768

Falla la comunicación CAN

Si se detectara el código de avería arriba mencionado y se encendiera el testigo luminoso del ABS, puede deberse a un fallo de la unidad de control del ABS/ESP en el suministro de tensión.

En este caso deberá comprobarse el suministro de tensión, las conexiones y el cableado de la unidad de control del ABS.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.