

Seat Ibiza - Radiador de realimentación de gases de escape | HELLA

Seat

Ibiza (6J)

Fecha de fabricación: a partir de 2009

Motor: 1,6 TDI

Radiador de realimentación de gases de escape

Se enciende el testigo luminoso de control del motor

Si en los vehículos arriba mencionados se registra una avería relacionada con la realimentación de gases de escape, puede deberse a un fallo en el radiador de realimentación de gases de escape.



· Posible coquización interna



Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.