

Fiat Nuova Punto - Allumage sporadique du témoin d'alerte ABS | HELLA

Fiat

Nuova Punto

Code moteur : 199 A3.000

Année modèle: 2005-2010

Allumage sporadique du témoin d'alerte ABS.

Le témoin d'alarme du système antiblocage des modèles mentionnés ci-dessus peut s'éclairer occasionnellement. Le code défaut P0504 est enregistré simultanément dans la mémoire des défauts du calculateur moteur.

Parfois, le témoin d'anomalie d'aide au démarrage en côte s'éclaire également.

Cause

Un blocage défectueux de la fiche du contacteur de pédale de frein peut être une cause possible de ce dysfonctionnement.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.