

Fiat Punto 199 - Bruits au niveau des freins | HELLA

Fiat Punto

Modèle, type199

Année modèle: 2005-2010

Bruits au niveau des freins arrière suite à des phases de freinage prolongées

Des phases de freinage prolongées peuvent entraîner des bruits de vibration au niveau du train arrière des modèles mentionnés ci-dessus.

Cause

Des oscillations de l'étrier de frein sont à l'origine de vibrations au niveau des plaquettes de frein.

Solution

Dans ce cas, le constructeur automobile propose des masses antivibratoires. La masse antivibratoire annule les oscillations involontaires et est installée directement sur l'étrier de frein.



Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.