

Opel Astra H - Fuite de réfrigérant | HELLA

Opel

Astra H

Année modèle : 2002 - 2009

Fuite de réfrigérant

Condenseur endommagé et non étanche

Si l'on observe une perte de réfrigérant sur le véhicule mentionné ci-dessus, le condenseur doit faire l'objet d'un examen particulier.

Des lamelles défailantes entraînent une instabilité du réseau condenseur. Des vibrations peuvent entraîner un contact avec d'autres composants. De ce fait, le condenseur est endommagé (figure 1) et le cas échéant non étanche.

En outre, il est possible que le condenseur se détache de sa fixation et soit en contact avec le support (figure 2). Ce qui peut également conduire à une fuite.




Figure 2



Figure 2

Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.