

# VW Golf IV - Fonction de recirculation d'air | HELLA

VW

Golf IV

avec climatisation manuelle

## Fonction de recirculation d'air

Sur les véhicules mentionnés ci-dessus, on peut éventuellement observer une prétendue défaillance de la fonction de recirculation d'air.

Le voyant du bouton de recirculation d'air (figure) peut, sur ces véhicules, tomber en panne prématurément. Cela amène à supposer qu'il existe un défaut électrique sur le bouton.

Avant de remplacer le bouton ou de procéder à une recherche complète des défauts, la lampe à incandescence doit faire l'objet d'un contrôle de fonctionnement et/ou être remplacée.



The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.