

BMW Serie 5 (G30/G31) / Serie 7 (G11/G12) - La luce stop risulta costantemente accesa | HELLA

BMW


Serie 5 (G30/G31) / Serie 7 (G11/G12)

Anno di costruzione: 05/2017

Con cambio automatico

La luce stop risulta costantemente accesa

Se si rileva il problema succitato, esso può essere dovuto a un difetto della testina sferica del pedale del freno.



ⓘ Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.