

FIAT Nuova Punto - Accensione sporadica della spia dell'ABS | HELLA

FIAT

Nuova Punto

Codice motore: 199 A3.000

Anni di costruzione: 2005-2010

Accensione sporadica della spia dell'ABS

Nei modelli del veicolo succitato può succedere che si accenda sporadicamente la spia di segnalazione del sistema antibloccaggio dei freni. Nel registro degli errori della centralina del motore viene memorizzato il codice di guasto P0504.

In alcuni casi si accende anche la spia di guasto dell'hill holder.

Causa

La causa di questo problema può essere rintracciata nel blocco dei contatti maschio del connettore dell'interruttore del pedale del freno.

ⓘ Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.