

Peugeot 307 - Spia dell'ABS accesa | HELLA

Peugeot

Modello: 307

Anni di costruzione: a partire dal 2006

Tutti i modelli con ABS/ESP

Spia dell'ABS accesa

Codice di guasto: 53768

Comunicazione CAN difettosa

Se si riscontra il guasto sopraindicato in concomitanza con una spia ABS lampeggiante, ciò può essere dovuto a un difetto dell'alimentazione elettrica della centralina dell'ABS/ESP.

In questo caso occorre controllare l'alimentazione elettrica, i connettori e il cablaggio della centralina dell'ABS.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.