

Opel Meriva - Regulación de la temperatura del habitáculo | HELLA

Opel

Meriva

Fabricados a partir de 2004 Con climatizador automático

Regulación de la temperatura del habitáculo

Es posible que en los vehículos arriba mencionados no pueda regularse la temperatura del habitáculo.

De las toberas de ventilación sale solo aire frío o muy caliente.

Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.