

Renault Clio - Dimlicht werkt niet | HELLA

Renault

Clio 2, 1.5D dCi

Motor: K9K 704

Bouwjaar: 2001 - 2006

Dimlicht werkt niet

Defect relaiscontact

Is bij bovenstaande voertuigen het dimlicht uitgevallen, kan dit met een verkeerde positionering van het dimlichtrelais in de relaissokkel samenhangen. Omdat het relais in de voetenruimte van de rijder onder het handschoenvak is aangebracht, kan de storing door "voetcontact" van de rijder zijn veroorzaakt. In dit geval moet de positie, bevestiging en het stekkercontact van het relais worden gecontroleerd en eventueel worden hersteld. Hierbij wordt het aanbevolen het relais ook vast te zetten op de relaissokkel met een trekband.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.