

Saab 9-3 - Koelvloeistofverlies | HELLA

Saab

9-3


Sedan/stationcar

Motorcode B284.

Chassisnummer: 61000001 – 81107480.


Koelvloeistofverlies

Bij bovengenoemde voertuigen kunnen klachten over lekkage van koelvloeistof voorkomen. Een mogelijke oorzaak hiervan is een defect aan het koelvloeistofexpansievat of beschadigde motorkoelvloeistofslangen aan het koelvloeistofexpansievat.



Het probleem kan worden verholpen door het koelvloeistofexpansievat te vervangen en de slangen van het koelvloeistofexpansievat te vervangen en opnieuw te rangschikken.

De autofabrikant biedt hiervoor gemodificeerde koelvloeistofslangen aan (zie afbeelding 2).



- 1*set motorkoelvloeistofslangen

Reserveonderdeelnr.:12 759 330

Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.