

Citroën C2/C3 Pluriel — Avaria da luz dianteira | HELLA

Citroën C2/C3/C3 Pluriel Ano de fabrico: 2006/10–2008/03 Avaria da luz dianteira
Nos veículos supracitados, é reclamada a avaria dos faróis. Esse erro pode dever-se a um erro no software do módulo de comando do sistema de iluminação. Possivelmente, a posição do interruptor das luzes não é identificada pelo módulo de comando, dando origem à avaria da iluminação dianteira. O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. No entanto, deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados. Na oficina especializada, é realizada uma atualização do software dos veículos afetados, a fim de resolver o problema.

C2 / C3 / C3 Pluriel

Model year: 10/2006 – 03/2008

Failure of the front light

The complaint has been made that the front headlight fails in the above vehicles.

The above problem with the lighting system may be caused by faulty ECU software.

The light switch position may not be detected by the ECU and thus leads to a failure of the front lighting.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

To remedy the above problem, the software needs to be updated at the relevant vehicles by a specialist workshop.