

Ford Galaxy VX, VY — Indicação de luz de travão com defeito | HELLA

Ford Galaxy VX, VYS-Max com spoiler traseiro
Ano de fabrico: 2006/02–2010/10
Indicação de luz de travão com defeito
Nos veículos supramencionados, a indicação “Luz de travão com defeito” brilha no ecrã de informações. Após uma inspeção visual, é detetado um defeito na terceira luz de travão (Figura 1.).
Figura 1. A causa pode ser uma rutura de cabo (Figura 2.) na área da passagem do cabo (luz de travão da porta da bagageira).
Figura 2. Para retificar o problema, a cablagem deve ser reparada ou substituída corretamente.

Galaxy VX, VY

S-Max with rear spoiler

Model year: 02/2006-10/2010

Brake light display faulty

In the above vehicles, "Brake light faulty" lights up on the info display.

Following a visual inspection, a defect is discovered on the third brake light (image 1).



Image 1.

The reason for this may be a break in the cable (image 2) around the cable bushing (tailgate brake light).



Image 2.

To remedy the problem, the cable harness should be professionally repaired or replaced.