

Informação do produto — Calços de travão Toyota | HELLA

Informação do produto Calços de travão Toyota 8DB 355 014-881 substitui 8DB 355 013-741 Nova atribuição de calços de travão Devido a alterações no equipamento de série do fabricante automóvel Toyota, a seguinte atribuição do artigo foi alterada da forma descrita a seguir. O calço do travão 8DB 355 013-741 / T1747 é substituído pelo calço do travão 8DB 355 014-881 / T1905. Aviso O material 8DB 355 013-741 / T1747 em stock pode ser ainda vendido. Aviso de montagem A diferença visível entre os dois calços de travão consiste no novo formato do revestimento de fricção (A).

Toyota brake linings

8DB 355 014-881 replaces 8DB 355 013-741

New allocation of the brake pads

Due to changes in the serial equipment carried out by the vehicle manufacturer Toyota, the following article allocation has been adapted as described in the following.

Brake pad 8DB 355 013-741 / T1747 will be replaced by brake pad 8DB 355 014-881 / T1905.

Note


Existing warehouse goods 8DB 355 013-741 / T1747 can still be sold.

Mounting instructions

The visible difference between both brake linings is the changed shape of the friction pad (A).

8DB 355 013-741 / T1747 (old)

8DB 355 014-881 / T1905 (new)



Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.