

Lexus IS F — Avaria do limpa-vidros | HELLA

Lexus IS F Ano de fabrico: 2007/07–2011/07 Avaria do limpa-vidros. Se, no veículo supramencionado, for reclamada a avaria do limpa-vidros, esta pode dever-se a um defeito no braço do limpa-vidros. Neste caso, o binário de aperto insuficiente das porcas do braço do limpa-vidros é responsável pela avaria do limpa-vidros. O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. No entanto, deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados. Na oficina especializada, as porcas do braço do limpa-vidros são substituídas e apertadas com o binário de aperto correto.

IS F

Model year: 07/2007 to 07/2011

Failure of the windscreen wipers.

If the windscreen wipers fail on the vehicle listed above, the cause may be a defect in the wiper arm.

In this case, insufficient torque in the wiper arm nuts is responsible for the failure of the windscreen wipers.

The vehicle manufacturer has already addressed the issue and notified owners of affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

The wiper arm nuts are replaced at specialist garages and attached with the correct torque.