

Mazda 3 — Avaria do limpa-vidros | HELLA

Mazda3Ano de fabrico: 2008.01.07–2009.03.31Avaria do limpa-vidrosSe, no veículo supramencionado, ocorrer uma avaria do limpa-vidros, tal pode ser indício de uma ligação à massa insuficiente do motor do limpa-vidros.Para resolver este problema, na oficina especializada, é instalado um cabo de massa adicional para o motor do limpa-vidros.O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados.No entanto, deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados.

3

Model year: 07/01/2008-31/03/2009

Windscreen wiper fails

If a complaint is made about the windscreen wiper failing in the above vehicle, this may indicate an insufficient earth connection in the windscreen wiper motor.

In order to remedy this, an additional earth cable for the windscreen wiper motor is mounted in the specialist workshop.

The vehicle manufacturer has already addressed the issue and notified owners of affected models.

For various reasons, however, it must be assumed that not all vehicles have been checked or modified.