

Mazda 5 — Ruídos nos difusores centrais | HELLA

Mazda **Mazda 5** **Ano de fabrico:** 2010 até 2012 **Ruído dos difusores centrais na área do painel de instrumentos** **Nos veículos supramencionados, podem ocorrer ruídos/vibrações dos difusores centrais na área do painel de instrumentos durante o funcionamento do aquecimento/ar condicionado.** Este efeito aumenta a velocidades de rotação elevadas do motor. A causa desta situação é uma falha de funcionamento relacionada com a conceção dos difusores centrais do painel de instrumentos para o aquecimento ou o ar condicionado. O problema já foi resolvido pelo fabricante do veículo, que oferece um difusor central modificado do painel de instrumentos (ver tabela). **Peças sobressalentes (ET)** **Descrição N.º ET** **Quantidade** **Ar condicionado/Aquecimento** **Difusor central do painel de instrumentos, direito** C513 64 930A1 **Difusor central do painel de instrumentos, esquerdo** C514 64 930A1

Mazda 5

Model year: 2010 to 2012

Noise coming from the centre air nozzles in the dashboard area

With the above-mentioned vehicles, noises/vibrations can occur in the centre air nozzles in the dashboard area when the heating/air conditioning system is switched on. This effect is amplified at high speed.

This is caused by a construction-related malfunction in the dashboard centre air nozzle for the heating and air conditioning system.

The vehicle manufacturer has already recognised the problem and is offering a modified dashboard centre air nozzle (see table).

Spare parts (SP)